






Use plastic
gray card
substance




To create hexagonal 3D forms
I created a mold of plasticine
over gray card, with foam at
wood in plastic sheet and
placed it into a vacuum
furnace heats up plastic
of heater then forcing in
vacuum it softens the plastic
around the form.

Use press saw to
cut at plastic and
then using disk sander
smoothed out edges.











MAKE-UP

MODELS



